

FLYING EXPERIENCE

22 November 1944

Approx. 1715

PILOT'S NAME
HOURS FLYING EXPERIENCE

NAME AND RANK OF PILOT **STRANDT, Kenneth Louis, Ens.**

SERVICE AND GROUP **(A1) 1. USNR**

ORGANIZATION **VF-22 (US COMPENS)**

DATE OF PILOT RATING

FLYING EXPERIENCE (YEARS)

MRS. THIS MODEL LAST 3 MOS

TOTAL HOURS

PREVIOUS ACCIDENT RECORD

INJURIES **Fatal**

NAME AND RANK OF OTHER PERSONNEL

INJ.

NONE

LOCATION **At sea.**

PURPOSE OF FLIGHT **Routine air patrol.**

FLYING OR LANDING CONDITIONS **Approx. 1 hr. 45 min.**

E-1 - Loss of power

PP - And - Failed on wave off.

ANALYSIS

as in report: after taking, main wave - off, pilot proceeded by ship on port side. Loss of power then resulted in plane losing sufficient alt. to contact water. Pilot did not get out & plane sank before ship could arrive.
RH

AIRCRAFT CLASS

MODEL AND NUMBER

FP-5 # unknown # 70039

DAMAGE A B C D E M

REMARKS

AIRPLANE

ENG. 1

ENG. 2

ENG. 3

ENG. 4

ENG. 5

ENG. 6

Sank at sea.

NATURE OF ACCIDENT

E

(water)

PERCENTAGE EACH CAUSE

U. S. NAVY
BUREAU OF AERONAUTICS

AIRCRAFT TROUBLE ANALYSIS

FORM N. AER. 339-A