6923

EMADORAS. Lt. Gol., AC MURROLE, Capt., AC MR 15 1046

T/O Charles J. Harder

1st Lt Walter C. Rowan

lat M: Jeseph S. Principe

1st Lt Ulna H. Syler

2nd Lt Sam Camp, Jr.

T/Egt Francis R. Keefe

T/Egt Wichael G. Vetrecin

8/8gt Clarence W. Diekerson

8/8gt Jess M. Hitchcook

8/Sgt William W. Waters, Jr.

8/8gt Ruben C. Miller

Mrs. Ruth M. Harder/ (Wife) 3136 West Mational Avenue, Milwandes, Wisconsin.

Mrs. Grace M. Rown, (Hife) 23519 Cayuga Street, Hessel Park, Michigan.

Mrs. Louise Princips, (Nother) 1432 28th Avenue, Long Island City, New York.

Mrs. Wilm L. Syler (Wife) Ossain Street, Densville, New York.

Mrs. June M. Gamp, (Wife) 414 West Grand Avenue, Decatur, Illinois.

Mrs. Grace A. Reefe, (Nother) 451 Lexington Street, Auburndale, Mas chusetts.

Mrs. Susen B. Vetreein, (Mother) 2605 Shirley, Youngstonn, Ohio.

Mrs. Wellis H. Dickerson, (Mother) Box 23, Oak Hill, West Virginia.

Mrs. Margaret F. Carter, (Sister) 1993 Elwood, Pomena, California.

Mrs. Ferne L. Waters, (Mother) 321 Cherry Street, Pine Bluff, Arkenses.

Mr. Zeno E. Miller, (Fother) 111 Moures Avenue Southeast, Canton, Chio. by E. A Pr. School Lt. Col., AC by F. M. BOWN H, Cart., AC Bato MAR 121946

WAR DEPARTMENT HEADQUARTERS ARMY AIR FORCES WASHINGTON

MISSING AIR CREW REPORT

IMPORTANT: This report will be compiled in triplicate by each army hir Forces organization within 48 hours of the time an aircraft is officially reported missing.

	and the second second second	anoll ma		3711 41 7
	ORGANIZATION: Location	APO# 719 ; Command or	Air Force	13th Air Porce
	Group 30/ch Bonts (h)	; Squadron 370th Bomb (H)	; Detach	ment None ;
- 0				
14	intended Destination			
•	WEATHER CONDITIONS AND	VISIBILITY AT TIME OF CRASH OR	WHEN LAST	REPORTED:
	CTUE: (c) Date 7 15 44	tus at 15,000, .2 Low cumulus, TimeApprox. 1220K; and Lo	tops 3000	visibility 1-2 miles
o	GIVE: (a) Date 1-10-74	of last know whereabout		
	The Specific what	ner () Last Sighted; () Last		
	() Forced Down	(X) Seen to Crash, or () Infor	rmation not	nvailable.
.i.		BELIEVED TO HAVE BEEN LOST,		
		iroraft () Enemy Anti-Aircra		
		ollision between AP# 42-73119		

٠,	IRCR.FT: Type, model a	and Series B-24J : A.A.F. Ser	rial No. 44	40556
	ENGINES: Type, Model and	Series R-183065A : A.A.F. Ser	rial No. (a	
	(b) BP-439965	; (c) BP-439987 sh below Make, Type and Soria	(d) BP-	137737
3.	INSTALLED VELPONS (Furni	sh below Make, Typo and Soria.	l Humber)	
	(a) 10-50 Cal. Browning	(b)Machine Guns. ; (c)(M=2) Se	erial number	
120	(e); (; (1	n)
9.	THE PERSONS LISTED BELOV	WERE REPORTED S: (a) Battle		Yes.
10-	AND AND AND PRINCIPLE AND	or (b) Non-Battle Co		
10:		D .IRCR.FT: Crew 11; Passenge		Total 11
		furnish the following particular restriction		
	and attach original t		tars on sepa	arato sheet
	and accach original t	Name in Full		Serial
	Crew Position	(Last Name First)	Rank	Number
	CLOW LOST CLOH	(Mast numb First)	REITE	Mulliper
1.	Pilot	SYLOR, ULNA H.	lst.Lt.	0-803306 MIA
2.	Co-Pilot	CAMP. SAM JR. V	2nd. Lt.	0-596746 MAR
3.	Navigator	PRINCIPE. JOSEPH S. J	latelite	0-689581 MIH
5.6	Bombardier	ROWAN WALTER C. /	lataLta	0-673904 MIR MIR
	Engineer	Vetrecin, Michael G. Jr.	T/Sgt.	18320307 Vis 3 20307
3.	Ass't Engineer	Hiller, Ruben. O	S/Sgt.	15323660 MIA
	Radio Operator	Keefe, Francis. R.	T/Sgt.	11116730 MIA
Je	Ass't Radio Operator	Waters, William W. Jr.	S/Sgt.	18168122 MIA
	Gunner	Hitchcook, James. H.	S/Set.	39256020 M A
	Gunner	Dickerson, Clarence, We V	S/Set	35442185 MIA
11.		RSONS WHO WE BELIEVED TO HAVE		EDGE OFIR-
	CRAFT, AND CHECK APPROP	RIATE COLUMN TO INDICATE BASIS	FOR SAME:	i
				CONTROL OF THE PROPERTY OF THE



MISSING AIR CREW REPORT - (continued)

	. %		Check only One Column			
		. <u>.</u>	ontacte	d		Sow
Name in Full (Last Name First)	Rank	Serial Number	By Radio	Last Sighted	Saw Crash	Forced Landing
HOBSTETTER, JAMES P	lst.Lt.	0-661489			X	WASCONE SOLVED FINAL SOLVE SERVICE - 1200 SO
KRUM, GEORGE W.	Corp.	39605884			X	
ALTIERI, RAYMOND R.	Corp.	32840591				
					Attached S	tetements

12. IF PERSONNEL ARE BELIEVED TO HAVE SURVIVED, ANSWER YES TO ONE OF THE FOLLOW-ING STATEMENTS: (a) Parachutes were used Yes; (b) Persons were seen walking away from scone of crash ; or (c) Any other reason (Specify)

13. ATTACH AERIAL PHOTOGRAPH, MAP, CHART, OR SKETCH, SHOWING APPROXIMATE LOCK-TION THERE AIRCRAFT WAS LAST SEEN.

14. ATTACH EYEVITNESS DESCRIPTION OF CRASH, FORCED LANDING, OR OTHER CIRCUMSTANCES PERTAINING TO MISSING AIRCRAFT.

15. ATTACH A DESCRIPTION OF THE EXTEND OF SEARCH, IF ANY, AND GIVE WAIE, RANK AND SERIAL NUMBER OF OFFICER IN CHARGE HERE

Date of Report

(Signature of Preparing Officer)
IRVING H. WATERMAN, JR.

REPRODUCED BY: 307TH BOMBARDMENT GROUP (:i) S-3 lst.Lt. Air Corps, JULY 1, 1943 Operations Officer.

Ref WD Ltr AG-360,33 (5-21-43) OB-S-AF-M (For instructionssee FEAF Reg 35-45)

CONFIDENTIA

71)

AG 360.33 (19 July 44)

3rd Ind.

HEADQUARTERS, FAR EAST AIR FORCES (P), A.P.O. 925, 2 August 1944.

TO: Commanding General, USAFFE, A.P.O. 501.

l. Records at this headquarters are in disagreement with the attached Missing Air Crew Reports in the following instances:

a. Records at this headquarters indicate Flight Officer HARDER's middle initial to be \underline{J} rather than $\underline{\hat{A}}$.

b. Records at this headquarters disclose that Technical Sergeant VETRECIN's army serial number is, 15320307, instead of 13320307.

i. Records at this headquarters fail to show Second Lieutenant DIEDERICH to be a Junior.

d. Records at this headquarters reveal that Corporal DUNBAR is a Junior.

e. Records at this headquarters indicate the army serial number of Sergeant CROWLEY to be 15004052 rather than 16004052.

For the Commanding General:

2 Incls: n/c.

Level C. Wood,
HERBERT C. WOOD,
Captain, A.G.D.,
Asst. Adj. Gen.

CONFIDENTIAL

80129

A-3/GLH/ans

360.33 lst Ind. HEADQUARTERS XIII BOMBER COMMAND, APO #719, 21 July 1944.

TO: Commanding General, Thirteenth Air Force, APO #719.

Searches were not carried out for possible survivors of this dual accident due to the location and intensity of the crash.

For the Commanding Officer:

W. H. INGLE, Lt. Col., A.G.D., Adjutant General.

2 Incls:

2 Incls: n/c

n/c

AG 704 24 Ind HEADQUARTERS THIRTEENTH AIR FORCE, APO 719, 23 July 1944.

G/3/ejc

TO: Commanding General, Headquarters Far East Air Forces, APO 925.

For the Commanding General:

C. C. HAVEN, 1st Lt., AGD,

Asst Adj Gen.

013775



8029 BBC 1500 7-20

HEADQUARTERS 307 FH BOMBARDMENT GROUP (H) Office of the Commanding Officer

NW/elo

APO # 719, 19 July 1944.

SUBJECT: Letter of Transmittal.

TO Commanding General, Headquarters Army Air Forces, Mashington, 25, D.C. (THRU CHANKELS).

1. Transmitted herewith, Missing Air Crew Reports of Lieutenants Diederich and Sylor and crews, missing in action on 15 July 1944;

For the Commanding Officer:


Captain, Air Corps, Asst. Adjutant.

2 Incl:

Incl #1 - Missing Air Crew Rpt, re: Lt. Sylor, 370th Bomb Sq (H).

Incl #2 - Missing Air Crew Apt, re: Lt. Diederich, 372nd Bomb Sq (H).





FEXC 360.33 (19 Jul 44)

4th Ind.

HQ UNITED STATES ARMY FORCES IN THE FAR EAST, A.P.O. 501, 7 August, 1944. TO: Commanding General, Army Air Forces, Washington 25, D. C. (ATTENTION: Statistical Control Division)

Forwarded in compliance with War Department letter dated 23 May, 1943, file AG 360.33 (5-21-43) OB-S-AF-M, subject: "Missing Air Crew Report".

For the Commanding General:

D. F. ROSS 2d Lt, AGD Asst Adj Gen

2 Incls:



21112 11 20 FF

AC# BR- 26253

370TH BOMBARDMENT SQUADRON (H)
Office of the Operations Officer
APO# 719

17 July, 1944.

1. Eyewitness description of crash, as the result of collision between AP42-73119, B-24J and AP# 44-40555, B-24J ever the target of YAP on 15 July, 1944 at 1220%, as seen by Corporal Kruz, George W., 39605884, 370th Bomb Squadron, flying A-1 in the 370th Squadron Formation.

"About three or four minutes prior to the collision I took note of the close formation immediately behind our plane and while I was then watching a green B-24 flying in C-3 position almost collided with C-1, probably as a result of prop wash, but the C-3 plane managed to right his plane into position again so I resumed watching the Zeros. I kept thinking about how close the planes (B-24's) were flying behind us and after a couple of minutes I swung the turret around to have another look, what I witnessed was this:

The B-24's were in even a closer formation and all at once the B-24 in C-3 position banked steeply to the right and up and struck the plane flying C-1 position, with the first contact being made by the props of C-3 plane against the bottom of the fuselage just behind the wing section of C-1 plane, as it began chewing its way through the fuselage proper.C-3 plane then began exploding from both wings and the planes both went to pieces.

The complete wing sections of both planes stuck together in sort of a "X" design and fell separately. The wing section of C-3 plane broke out in flames and explosedas soon as it hit C-1 plane-it fell fairly well in pieces as it descended. C-1's wing section fell in one piece in sort of a falling leaf pattern and seemed little hurt-being apparently intact from the nose section to just behind the wing and fuselage point where it had been chewed in two. Some turrets from both planes were thrown from their wells and were left to fall clear with other pieces of the wreckage. When we were at about a mile or so from whore the accident occurred chutes began to open at about 8000'. I would say at least five of them puffed into view in quick succession. By then the Zeros were making passes at ours and surrounding B-24's as fast as they could so I left off watching the falling chutes to fight off the attacks being made on the bottom of our ship. Bombs were away at 1211K and the approximate time of the collision was at 1220K. I am the ball gumner on the crew of Lt. Gage and an reporting this as an eyewitness account of what I saw."


GEORGE W. KRUM, Corporal, Air Corps. 370TH BOMBARDMENT SQUADRON (H)
Office of the Operations Officer
APO# 719

17 July, 1944.

1. Eyewitness description of crash, as the result of collision between AP# 42-73119 and AP# 44-40555 both E-24J's over the target of YAP on 15 July, 1944 at 1220% or thereabouts, as seen by Corporal Raymond R. Altieri, tail ganner on AP# 42-110075 370th Bomb Squadron.(Lt. Gage's Crew).

"I didn't see the crash itself but I noticed the pieces flying by our tail. The wings were interlooked and were going down in flames, the biggest pieces I noticed was the tail end of the fuselage of the last ship. This rice extended from the waist window to the tail. I noticed four bodies tumbling down and one parachute open also and empty life raft. Most of the parts were burning when they hit the water and were pouring black smoke. After we were out of sight of the wreckage I saw a large column of gray smoke rise above some clouds."

Corporal, Air Corporal Collini



17 July, 1944.

1. Eyewitness description of crash, as the result of collision between AP# 42-73119, B-24J and AP# 44-49555, B-24J over the target of YAP on 15 July, 1944 at approximately 1220K as seen by Lt. Hobstetter, James P., 0-661489 Lt. Hobstetter was flying C-2, 370th Bomb Squadron at the time of the collision.

"The crash involving Lt. Sylor occurred shortly after our withdrawal from the target area, the exact distance from this area I cannot accurately say. The leader of our squadron was pulling up on the right of a seven ship formation lead by the group leader in an effort to present a group front to enemy interception. My position at the time was G-2: Lt. Sylor was approximately in a C-3 position with Lt. Diederich on his left wing.

I cannot expetiate further on the causes which resulted in the crash. I saw only the actual collision. The shipspiloted by Lt. Diederich crashed into Lt. Sylor striking him behind the flight deck. The left wing of Lt. Diederich's plane was torn away and Lt. Sylor's ship was severed in half just back of the flight deck. Both planes burst immediately into flames and wont down. Although reports indicate that several men bailed out of the burning planes no parachutes were observed by themembers of my craw. As I have previously stated I cannot obviate the apparently enigmatic conditions which resulted in the collision. However, I can state that the crash did not occur from overrunning of the two squadrons represented in the group front.

JAMES P. HOBSTETTER,

1st. Lieutenant, Air Corps,

Pilot.

CONF

S79TH BOMBARDMENT SQUADRON (N) Office of the Operations Officer APO# 719

17 July, 1944.

1. The presence of Flight Officer CHARLES A. HARDER, A.S.W. T-124507, on AP# 44-40555 on 15 July, 1944 is accounted for in the following manner.

"It has been the Squadron Policy to indoctrinate new combat Officers in this area by permitting them to fly as the eleventh man en a crew in the capacity of an Observer. This is the situation which obtained on 15 July, 1944 at 1220K when AP# 42-75119 and AP# 44-4055E which collided over the target of YAP ISLAND, necessitated this report."

IRVING H. WATERMAN, JR.
1st. Lieutenant, Air Corps,
Operations Officer.

CREW POSITION	name in full (Last name first)	RANK	RANK NUMBER		
Navigator	HARDER, CHARLES	F/O	T-124507		

OFFICE OF THE QUARTERMASTER GENERAL OF THE ARMY

INTEROFFICE REFERENCE SHEET

MY # 923 MACK

DUE, HOUR AND DATE				
No.	FROM-	TO-	DATE	MESSAGE
1	Search Info Ident	QM 29 Pentagon July Liaison 1948	1., Request latest status & date of following personne . MACR #6923	
	Branch	-101001	1010	Status Date
				Sylor, Ulna H. 0-803306 _ De D 30 Mary6
	OSTON			Camp, Sam Jr. 0-696746 De D 30 NO 146
		5		Principe, Joseph S. 0-689581 De B 30Mary6
				Rowan, Walter C. 0-673904 DeD 30 MOVY6
		•		Vetrecin, Michael G. 15320307 De D 33Mar 46
				Miller, Ruben 0. 15323660 - DeD 3 ONAV 46
				Keefe, Francis R. 11116730 PCD 30 May 46
	, i			Waters, William W. 18168122 - DeD 30 May 46
				Hitchcock, James M. 39256020 DeP30 Mar 46
				Dickerson, Clerence W. 35442185 -Dep 30Mar, 46
				2. Request check on correctness of serial number for Vetrecin, Michael G. as 15320307
				Sull i v an
				72000

THIS FORM WILL REMAIN PART OF THE OFFICIAL FILE
U. S. GOVERNMENT PRINTING OFFICE: 1946-0-708275-136

